TECHNICAL BULLETIN
014
December 2016

Check valve cages p.n. 1407.51

1407.51 was *1407.51 is*



The fitting has been modified to improve the durability of the valve seat components in case of large flow rate in by-pass.
The new fitting is interchangeable with the old.
Other parts of the valve are not changed.
The part numbers remain the same.

LEUCO S.p.A. - VIA P. COLLETTA, 20 – VILLAGGIO CROSTOLO - 42124 REGGIO EMILIA – ITALY
E.C. VAT registration number: IT 00607420353 - C.F. e Iscrizione al Registro Imprese di RE n. 00607420353
TEL: +39 / 0522 / 923011 – FAX: +39 / 0522 / 923030 - E-mail: info@hawkpumps.com – http:// www.hawkpumps.com
Società soggetta all'attività di direzione e coordinamento di Kärcher Beteiligungs GmbH

TECHNICAL BULLETIN
014
Dicembre 2016

Raccordo codici 1407.51

1407.51 era

1407.51 è



Il raccordo è stato modificato per migliorare la durata dei componenti della sede valvola nel caso di portata in larga parte in by-pass.
Il nuovo raccordo è intercambiabile con il vecchio.
Le altre parti della valvola non sono cambiate.
I codici rimangono gli stessi.

LEUCO S.p.A. - VIA P. COLLETTA, 20 – VILLAGGIO CROSTOLO - 42124 REGGIO EMILIA – ITALY
E.C. VAT registration number: IT 00607420353 - C.F. e Iscrizione al Registro Imprese di RE n. 00607420353
TEL: +39 / 0522 / 923011 – FAX: +39 / 0522 / 923030 - E-mail: info@hawkpumps.com – http:// www.hawkpumps.com
Società soggetta all'attività di direzione e coordinamento di Kärcher Beteiligungs GmbH